

Declassification Review by NGA/DoD

OUT51697

PRIORITY

P 162131Z

1963 AUG 16 22 22Z

FM CIA WASHDC

19 AUG 1963

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

RUCVAB/4080TH STRAT WG, OL 19, BARKSDALE AFB, LA

RUEAHQ/DIAXX

RUECYG/NAVY PIC

RUWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF.

RUWGAA/2AF, BARKSDALE AFB, LA

RUWGAA/2D RTS, BARKSDALE AFB, LA

DA GRNC

BT

HFS HS
CJS JS
GFC JS
FND JS
ACL JS

Grace (File))

S E C R E T

CITE CIA-Z-820

15TH AF (FOR DI); SAC (FOR DIM, BRASS KNOB, DOCR, DM4), 2D AF (FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

1. CAMERA B 15 WAS USED IN MISSION 3692 FLOWN ON 15 AUGUST 1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: THERE IS A CREASE 3.5" FROM THE INBOARD EDGE IN THE FIRST 20 FRAMES. AN OBSTRUCTION CAUSED BY A WIRE ADJACENT TO THE DATE CHAMBER IS NOTED THROUGHOUT THE MISSION. THE POSITION INDICATOR LAMPS ARE UNDEREXPOSED. THERE IS A CREASE STARTING AT A MANUFACTURER'S SPLICE IN FRAME 1305 THAT CONTINUES TO FRAME 1337. A SERIES OF MINUS DENSITY DOTS ARE NOTED IN THE FIRST 40 FRAMES. THESE DOTS ARE 1.5" APART AND LOCATED 0.6" FROM THE INBOARD EDGE.

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

C. 9L SIDE: THERE IS AN EMULSION LIFT IN FRAME 3 AND A SERIES OF MINUS DENSITY DOTS 1.5" APART AND LOCATED 0.62" FROM THE INBOARD EDGE IN THE FIRST 600 FRAMES. LIGHT PRESSURE ROLLER STATIC IS INTERMITTENT FROM FRAME 79 TO THE END OF THE MISSION ALONG THE INBOARD EDGE.

D. MINOR PROCESSING STREAKS OCCUR ON BOTH SIDES THROUGHOUT THE LAST 600 FRAMES. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES NOTED ON THIS MISSION. THERE ARE A TOTAL OF 2420 FRAMES IN THIS MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD. THE PRINTING AND PROCESSING OF THE POSITIVES WAS GOOD.

B. CLOUDS COVERED 10-15 PERCENT OF THE MISSION.

SCP-1

S E C R E T

END OF MESSAGE

(ABOVE MESSAGE ALSO PASSED TO CIA WATCH ASP/RR)

1